

Z-type reducer 1arcmin/3arcmin

attachable with 100W~2000W servomotor

Z-type reducer 30 arcmin (a few items excluded)

attachable with 100W∼2000W servomotor

Concentric Hollow Shaft Type



Gear unit ratio1/10~1/60
(up to 1/120 only for 100w)

Gear unit ratio

Concentric Solid Shaft Type



Gear unit ratio1/10~1/60
(up to 1/120 only for 100w)

Gear unit ratio

Hollow Shaft Type



Gear unit ratio 1/80~1/240

Solid Shaft Type (Flange Mount)



Gear unit ratio

Solid Shaft Type (Foot Mount)



AH2L

Gear unit ratio

Parallel Shaft Type (Foot Mount)



AG3L

Gear unit ratio

Parallel Shaft Type (Flange Mount) Frame No.18~32



AG3K

Gear unit ratio

Parallel Shaft Type (Flange Mount) Frame No.40~50



AG3F

Gear unit ratio 1/30~1/200